

Improvement of Strength Characteristics of Road Surfacing in Timber-Felling Sites

E.V. Kondrashova

Voronezh State Forest Engineering Academy, Voronezh

Key words and phrases: soil dampness; water disposal; road surfacing strength; waysides condition.

Abstract: Some parts of automobile roads in timber-felling sites suffer from water stagnation along the waysides in spring and autumn seasons, thus lowering the strength of road surfacing by 20%. The paper presents the scheme of improving water disposal on automobile roads in timber-felling sites.